



NEVADA

LOUNGESET






NEN 581



442016.442031

Nevada table


2



442016.442027

Nevada seat



4




442027.442027

Nevada corner seat


8




TA (1x)




LA (2x)



LB (2x)





M (4x)





C2 (2x)




C3 (1x)







2




3




442016.442027




C2 (2x)




TA Ø4 (1x)



NB (1x)




LA (2x)




LB (2x)




C3 (1x)




M (2x)



M2 (2x)



H (1x)





J (4x)




L (1x)






R (4x)





TA Ø4





2




3





4




5







TA Ø8 (1x)




NB (2x)




LA (2x)




LB (2x)





M (1x)




M2 (2x)




M3 (1x)





H (2x)




C2 (2x)






C3 (1x)








2




3




4




5




6

















7




8




9





C2



C3

