



## **BELTON**





Coli	Тур	Ersatzteil:	Dimension
		BLA.101 x4	258x384x15
1/4	312	BLA.601 x2	267x620x2,5
		BLA.701 x2	628x267x16
	481	BLA.204 x2	1885x352x15
		BLA.503 x6	259x329x15
		BLA.605	1881x268x2,5
Coli	Тур	Ersatzteil E	Dimension
	1.76	H Nummer	
2/4	312	BLA.201 x2	1250x404x15
		BLA.202 x2	1250x385x15
		BLA.301 x2	601,5x357x15
		BLA.501 x2	258x362x15
Coli	Тур	Nummer:	Dimension
		BLA.102	1087x288x15
		BLA.103	613x288x15
3/4	531	BLA.104	184x288x15
		BLA.203 x2	600x289x15
		BLA.302	567x251x15
		BLA.401 x 2	568x265x15
		BLA.502	290x264x15
		BLA.602	611x577x2,5
		BLA.603	300x294x2,5
		BLA.604	179x577x2,5
		BLA.702	193x596x16
		BLA.703	303x296x16
		BLA.704	622x596x16
Coli	Тур	Ersatzteil	Dimension ::::
	1.75	Nummer:	
4/4	533	BLA:105	1087x288x15
		BLA.106	613x288x15
		BLA.107	184x288x15
		BLA.203 x2	600x289x15
		BLA.302	567x251x15
		BLA.401 x 2	568x265x15
		BLA.502	290x264x15
		BLA.602	611x577x2,5
		BLA.603	300x294x2,5
		BLA.604	179x577x2,5
		BLA.705	193x596x16
		BLA.703	303x296x16
		BLA.707	622x596x16

















**BELTON** Typ 531 (BLA.203) (BLA.302) = BLA.203 (BLA.401) BLA.604) (BLA.104) BLA.702 (BLA.401) **BLA.603** BLA.502 BLA.703 (BLA.401) BLA.102 **BLA.103** BLA.302 BLA.704) BLA.602 BLA.203 6,5/68mm | +10x50mm +8x60mm +4.0x30mm +35/0mm +3.5x13mm **P8** 04 07 P5 2 +8x30mm L=2x128mm +4.0x27mm +3.0x20mm +15/12mm 0\_

S12

R1

01


Е


D2


20


20


20


































-715 mm--32,5 mm 6,5/68mm | +10x50mm Militar 1725 mm 8mm 715mm Bohrer +10mm 2







33

## **BELTON**











	+3.0x20mm
9/	
E	P7
24	4
_	<u>E</u> 24

