




FX 16 - skriňa úzka 3D



zoznam	rozмеры v mm	kusy
A	1914x360	2
B	450x360	1
C	450x360	1
D	414x356	2
E	414x356	1
F	638x356	1
G	229x350	2
H	167x356	1
I	177x297	1
J	162x356	1
K	247x356	1
L	747x447	1
M	470x356	1
N	1017x297	1
O	1938x438	1

a	b	c	d	e	f	g	o	p	s
x 6	x 3	x 6	x 28	3,5 x 12	x 6	x 12			
x 12	x 6	3,5 x 8	x 1	x 6	x 6	x 60		x 4	x 28
j	k	l	m	n	h	i		r	

POTREBNÉ NÁRADIE

